

Bob Kanza

PU Anderson 4/28

DETAILS ON NEG TEST D) C/P/AD NEG TEST
How TREC displaced
VALVE ARRANGEMENTS

- 4 Brian 1400 psi

[X] Toolpusher? with 3124?
3000- 3124 psi connected

1120/3000 system go return

ON TOWER learn for post neg test
xci 3.5
300

CULTURE -

Orientation - good here
Pr job safety integ. build

STOP THE JOB

TRAINING

SAFETY SCHEDULE OR SCHEDULE SAFETY

NEXT ASSIGNMENT

VANCE Carpenter Halliburton

William + Leo comfortable with going forward
Review Bob - Randy conversation

Drill pipe = 0 Bob opening kill line, How started
Cemented solid (Vance) verified flow, Bob shut down
Bob to talk to Dan.

where was shut in Bob or ?

Bob-Dan may have difficult time believing, must monitor on left side (Don)

- New toolpusher Jason Bushle w/15 hrs, long discussion

- Toolpusher said they stopped, Jason said "Don't Bob, this happened
the same"

Jason - all company men do negative test & Germany
when heavy visor & closed zimmer

Don - APD asked to do test via kill line, Jason - ok
Don Jason make sure kill line is full, then monitor them

Bob got better procedures for cement job from office

when Bob returned, 30 psi. showed

Pumped down kill line, closed off

Pressure building on drill pipe side

Leo pumping out sand traps, getting 500 bbl according to mud loggers

720 - 750 negative test - to bed

Fire alarm first recognizable alert, PA sounded
electricity off

an explosion. Bob to Joe, mud logger, Zesp - 2nd stronger
saw Don on deck, blood, appeared dead
- No gas, displacement perfect

Seafast way to do this? Neg test w/ gas based mud
Cement plug first

Room
310