

Continuing Erosion Did Not Affect Flow Rate:
Erosion of Blind Shear Rams




Fig. 144




Fig. 149




Fig. 147