Key Opinion #1

- Weatherford's data from rotary sidewall cores cannot be used to generate a reliable estimate of UPVC for the Macondo reservoir.
 - Due to poor core recovery and sample condition, tested cores were not representative.
 - Weatherford's flawed testing procedure on sidewall cores yielded unreliable data and underpredicted UPVC.

TREX-11698R D-21310