1. Weatherford test results relied on by Drs. Zimmerman and Blunt are not reliable and are underpredictive

a. Tested cores not representative

- 1. Low number of suitable samples relative to the size of the reservoir.
- 2. Evidence of sample damage from drilling process.
- 3. Well logs show that core properties were not representative of average reservoir properties.